



# F1045

## GUIDA PER PROFILO CON INSERIMENTO CORDONETTO

*Per macchine piane  
For flat bed machines*

Lavoro Finito (finished work)




**PIEDINO CONSIGLIATO**  
SUGGESTED FOOT



**G36069HL** - per tutte le misure  
(for all sizes)

### CORD EDGE PIPING ATTACHMENT



Codice	Entrata (A) (tape size)		Lav. finito (B) (finished size)		Spessore (S) (thickness)
	(mm)	(inch)	(mm)	(inch)	
<b>F1045/18M</b>	18	45/64	9	23/64	M
<b>F1045/19M</b>	19	3/4	9,5	3/8	M
<b>F1045/22M</b>	22	7/8	11	7/16	M
<b>F1045/25M</b>	25	1	12,5	1/2	M
<b>F1045/28M</b>	28	1-7/64	14	35/64	M
<b>F1045/30M</b>	30	1-3/16	15	19/32	M
<b>F1045/35M</b>	35	1-3/8	17,5	11/16	M

**NOTA: USARE CORDINI Ø 2 - 2,5 mm**  
NOTE: USE CORD Ø 2 - 2,5 mm